

FACILITY CONDITION ASSESSMENT



prepared for

Montgomery County Public Schools
45 West Gude Drive, Suite 4000
Rockville, MD 20850



Wayside Elementary School
10011 Glen Road
Potomac, MD 20854

PREPARED BY:

Bureau Veritas
6021 University Boulevard, Suite 200
Ellicott City, MD 21043
800.733.0660
www.bvna.com

BV CONTACT:

Bill Champion
Senior Program Manager
443.622.5067
Bill.Champion@bureauveritas.com

BV PROJECT #:

172559.25R000-127.354

DATE OF REPORT:

November 10, 2025

ON SITE DATE:

September 15, 2025

Bureau Veritas

6021 University Boulevard, Suite 200 | Ellicott City, MD 21043 | www.bvna.com | p 800.733.0660

TABLE OF CONTENTS

1. Executive Summary 1

Property Overview and Assessment Details 1

Campus Findings and Deficiencies 2

Facility Characteristic Survey 3

Facility Condition Index (FCI) Depleted Value 4

Immediate Needs..... 5

Key Findings 5

Plan Types..... 6

2. Building Information 7

3. Site Summary 10

4. ADA Accessibility 12

5. Purpose and Scope 14

6. Opinions of Probable Costs 16

Methodology 16

Definitions 17

7. Certification..... 18

8. Appendices 19



1. Executive Summary

Property Overview and Assessment Details

General Information	
Property Type	Elementary school
Number of Buildings	1
Main Address	10011 Glen Road, Potomac, MD 20854
Site Developed	1969, addition 2007, Renovated 2017 (demo and rebuild)
Outside Occupants / Leased Spaces	None
Date(s) of Visit	September 15, 2025
Management Point of Contact	Montgomery County Public Schools Greg Kellner Facilities Manager, Office of Facilities Management Direct 240.740.7746 Gregory_Kellner@mcpsmd.org
On-site Point of Contact (POC)	Miss Violeta E Alfaro Building Service Manager III Violeta_E_Alfaro@mcpsmd.org
Assessment & Report Prepared By	William Hunt
Reviewed By	Daniel White, <i>Technical Report Reviewer for</i> , Bill Champion Program Manager 443.622.5067 Bill.Champion@bureauveritas.com
AssetCalc Link	Full dataset for this assessment can be found at: https://www.assetcalc.net/

Campus Findings and Deficiencies

Historical Summary

The facility was built in 1969, and additional space was added in 2007. The original building was demolished and rebuilt in 2015-2017 with the exception of the 2007 addition left in place.

Architectural

The facility appears structurally sound, with no significant areas of settlement or structural-related deficiencies reported or observed. The roof membranes do not show any pressing issues. Overall, the exterior envelope systems and components are performing adequately. Interior finishes have generally been replaced as needed and are anticipated for lifecycle replacement based on useful life and normal wear. The gym floor appears to have been refinished in recent years, and the other finishes of the building are holding up adequately.

Mechanical, Electrical, Plumbing and Fire (MEPF)

Most of the HVAC equipment is original to the reconstruction date of 2017 and the prior addition date of 2007. Component replacements for split systems will be the first to reach lifecycle replacements in the next five-to-seven-year range. The roof has scattered exhaust fans, package units, and VRV units. These are generally functioning well, and no significant replacements are anticipated within the next eight to ten years and beyond. Boilers from 2016, a cooling tower, and an air handler supply treated air in other areas.

The plumbing systems are also a mix of original and replacement, and plumbing appears adequate for the facility, with equipment and fixtures generally updated as needed. A gas water heater supplies hot water throughout. No significant leaks or pressure issues were reported.

Electrical service equipment and systems appear generally adequate. A 2000A and 800A switchboard supply power throughout. There is a generator on the exterior for emergency power outages.

Fire alarm and suppression sprinkler systems are present throughout the facility.

Site

The facility's site includes asphalt paved parking and drive areas, as well as areas of concrete sidewalk. Part of the site perimeter is ringed by chain link fencing. Pole lights are present throughout the site.

Recommended Additional Studies

No additional studies recommended at this time.

Facility Characteristic Survey

The facility characteristics of school and associated buildings are shown below.

Indoor air quality, including temperature and relative humidity level is monitored centrally. Most instructional spaces are equipped with IAQ sensors. Each general and specialty classroom has a heating, ventilation, and air conditioning (HVAC) system capable of maintaining a temperature between 68°F and 75°F and a relative humidity between 30% and 60% at full occupancy. Each general, science, and fine-arts classroom had an HVAC system that continuously moves air and is capable of maintaining a carbon dioxide level of not more than 1,200 parts per million. The temperature, relative humidity and air quality were measured at a work surface in the approximate center of the classroom.

The acoustics with the exception of physical-education spaces, each general and specialty classroom are maintainable at a sustained background sound level of less than 55 decibels. The sound levels were measured at a work surface in the approximate center of the classroom.

Each general and specialty classroom had a lighting system capable of maintaining at least 50 foot-candles of well-distributed light. The school has appropriate task lighting in specialty classrooms where enhanced visibility is required. The light levels measured at a work surface located in the approximate center of the classroom, between clean light fixtures. The school makes efficient use of natural light for students, teachers, and energy conversation.

Classroom spaces, including those for physical education, were sufficient for educational programs that are appropriate for the class-level needs. With the exception of physical-education spaces, each general and specialty classroom contained a work surface and seat for each student in the classroom. The work surface and seat were appropriate for the normal activity of the class conducted in the room.

Each general and specialty classroom had an erasable surface and a surface suitable for projection purposes, appropriate for group classroom instruction, and a display surface. Each general and specialty classroom had storage for classroom materials or access to conveniently located storage.

With the exception of physical-education spaces and music-education spaces, each general and specialty classroom has a work surface and seat for the teacher and for any aide assigned to the classroom. The classroom had secure storage for student records that is located in the classroom or is conveniently accessible to the classroom.

The school was constructed with sustainable design practices. The schools use durable, timeless, low-maintenance exterior materials. The school's materials (particularly shell) should withstand time as well as potential impacts related to structural, site and climate changes.

The school is functionally equitable. All students in this school have access to safe, well-maintained, and appropriately equipped learning environments as students in other MCPS schools. As part of the evaluation factor, the MDCl will be presented upon final of all assessments.

Facility Condition Index (FCI) Depleted Value

A School Facility's total FCI Depleted Value (below) and FCI Replacement Value (above) are the sum of all of its building assets and systems values. A School Facility with full estimated life of all systems (a brand new school) would have a 0 FCI. The FCIs cannot exceed 1.

The Facility Condition Index (FCI) Depleted Value quantifies the depleted life and value of a facility's primary building assets, systems and components such as roofs, windows, walls, and HVAC systems. FCI Depleted Value metrics are useful for estimating the levels of spending necessary to achieve and maintain a specific level of physical condition. Lower scores are better, as facilities with lower FCI scores have fewer building-system deficiencies, are more reliable, and will require less maintenance spending on systems replacement and mission-critical emergencies.

The FCI Depleted Value of this school is 0.288223.

Immediate Needs

There are no immediate needs to report.

Key Findings


There are no key findings to report.

Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance and highest on the list below.

Plan Type Descriptions & Distribution

Safety	■	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
Performance/Integrity	■	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
Accessibility	■	Does not meet ADA, UFAS, and/or other accessibility requirements.
Environmental	■	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Retrofit/Adaptation	■	Components, systems, or spaces recommended for upgrades in order to meet current standards, facility usage, or client/occupant needs.
Aged But Functional	■	Any component or system that has aged past its industry-average expected useful life (EUL) but is not currently deficient or problematic.
Lifecycle/Renewal	■	Any component or system that is neither deficient nor aged past EUL but for which future replacement or repair is anticipated and budgeted.



10-YEAR TOTAL: \$2,670,800

2. Building Information



Building: Systems Summary

Address	10011 Glen Road, Potomac, MD 20854	
GPS Coordinates	39°02'51.45" N ; 77°12'22.86" W	
Constructed/Renovated	1969	
Building Area	93,453 SF	
Number of Stories	2 above grade	
<i>System</i>	<i>Description</i>	<i>Condition</i>
Structure	Masonry bearing walls with metal roof deck supported by open-web steel joists and concrete strip/wall footing foundation system	Good
Façade	Primary Wall Finish: Masonry facade Windows: Aluminum	Good
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted gypsum board, ceramic tile Floors: Wood, VCT, Carpet Ceilings: ACT	Fair
Elevators	Passenger: 1 hydraulic car serving both floors	Fair
Plumbing	Distribution: Copper supply and cast-iron waste & venting Hot Water: Gas water heaters with integral tanks Fixtures: Toilets, urinals, and sinks in restrooms	Fair

Building: Systems Summary		
HVAC	Central System: Boilers, cooling tower, air handlers feeding ductwork Non-Central System: Rooftop units, split systems, exhaust fans	Fair
Fire Suppression	Sprinkler system	Fair
Electrical	Source & Distribution: Main switchboard with copper wiring Interior Lighting: LED Exterior Building-Mounted Lighting: LED, CFL Emergency Power: Diesel	Fair
Fire Alarm	Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Fair
Equipment/Special	Commercial kitchen equipment	Fair
Accessibility	Presently it does not appear an accessibility study is needed for this building. See the appendix for associated photos and additional information.	
Additional Studies	No additional studies are currently recommended for the building.	
Areas Observed	A representative sample of the interior spaces were observed to gain a clear understanding of the facility's overall condition. Other areas accessed and assessed included the exterior equipment and assets directly serving the building, the exterior walls of the facility, and the roof.	
Key Spaces Not Observed	All key areas of the facility were accessible and observed.	

The table below shows the anticipated costs by trade or building system over the next 20 years.

System Expenditure Forecast						
System	Immediate	Short Term (1-2 yr)	Near Term (3-5 yr)	Med Term (6-10 yr)	Long Term (11-20 yr)	TOTAL
Structure	-	-	-	-	-	-
Facade	-	-	\$9,600	-	-	\$9,600
Roofing	-	-	-	\$887,200	-	\$887,200
Interiors	-	-	\$380,300	\$424,900	\$1,004,800	\$1,809,900
Conveying	-	-	\$5,500	\$11,100	-	\$16,500
Plumbing	-	-	-	-	\$366,400	\$366,400
HVAC	-	-	\$304,300	\$122,400	\$1,061,800	\$1,488,500
Fire Protection	-	-	-	\$17,700	\$165,300	\$183,000
Electrical	-	-	-	-	\$1,114,500	\$1,114,500
Fire Alarm & Electronic Systems	-	-	-	\$306,300	\$878,300	\$1,184,600
Equipment & Furnishings	-	-	\$49,100	\$43,500	\$118,700	\$211,300
TOTALS (3% inflation)	-	-	\$748,700	\$1,813,200	\$4,709,800	\$7,271,700

3. Site Summary



Site Information		
Site Area	7.8 acres (estimated)	
Parking Spaces	Approximately 80 total spaces all in open lots; 4 of which are accessible	
<i>System</i>	<i>Description</i>	<i>Condition</i>
Site Pavement	Asphalt lots with adjacent concrete sidewalks, curbs, and ramps	Fair
Site Development	Chain link fencing Playgrounds and courts Limited park benches	Fair
Landscaping & Topography	Landscaping features including lawns and trees Irrigation not present Low to moderate site slopes throughout	Fair
Utilities	Municipal water and sewer Local utility-provided electric and natural gas	Fair
Site Lighting	Pole-mounted: LED, HPS	Fair
Ancillary Structures	None	--
Site Accessibility	Presently it does not appear an accessibility study is needed for the exterior site areas. See the appendix for associated photos and additional information.	

Site Information	
Site Additional Studies	No additional studies are currently recommended for the exterior site areas.
Site Areas Observed	Most of the exterior areas within the property boundaries were observed to gain a clear understanding of the site's overall condition.
Site Key Spaces Not Observed	All key areas of the exterior site were accessible and observed.

The table below shows the anticipated costs by trade or site system over the next 20 years.

System Expenditure Forecast						
System	Immediate	Short Term (1-2 yr)	Near Term (3-5 yr)	Med Term (6-10 yr)	Long Term (11-20 yr)	TOTAL
Electrical	-	-	-	-	\$142,100	\$142,100
Site Development	-	-	\$50,700	\$5,100	\$34,900	\$90,700
Site Pavement	-	-	\$24,600	\$28,500	\$360,600	\$413,700
Site Utilities	-	-	-	-	\$33,200	\$33,200
TOTALS (3% inflation)	-	-	\$75,300	\$33,600	\$570,900	\$679,800

4. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the material included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this assessment. A full measured ADA survey would be required to identify more specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are not included in the dataset
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance

The following table summarizes the accessibility conditions of the general site and each significant building or building group included in this report:

Accessibility Summary			
<i>Facility</i>	<i>Year Built/ Renovated</i>	<i>Prior Study Provided?</i>	<i>Major/Moderate Issues Observed?</i>
General Site	1969/2017	No	No
Wayside Elementary School	1969/2017	No	No

No detailed follow-up accessibility study is currently recommended since no major or moderate issues were identified at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.

5. Purpose and Scope

Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

Condition Ratings	
Excellent	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

6. Opinions of Probable Costs

Cost estimates are embedded throughout this report, including the detailed Replacement Reserves report in the appendix. The cost estimates are predominantly based on construction rehabilitation costs developed by the *RSMeans data from Gordian*. While the *RSMeans data from Gordian* is the primary reference source for the Bureau Veritas cost library, secondary and supporting sources include but are not limited to other industry experts work, such as *Marshall & Swift* and *CBRE Whitestone*. For improved accuracy, additional research integrated with Bureau Veritas's historical experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions also come into play when deemed necessary. Invoice or bid documents provided either by the owner or facility construction resources may be reviewed early in the process or for specific projects as warranted.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

To account for differences in prices between locations, the base costs are modified by geographical location factors to adjust for market conditions, transportation costs, or other local contributors. When requested by the client, the costs may be further adjusted by several additional factors including; labor rates (prevailing minimum wage), general contractor fees for profit and overhead, and insurance. If desired, costs for design and permits, and a contingency factor, may also be included in the calculations.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system or component replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

7. Certification

Montgomery County Public Schools (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Wayside Elementary School, 10011 Glen Road, Potomac, MD 20854, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews with available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.


No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

Prepared by: William Hunt
Project Assessor

Reviewed by:



Daniel White
Technical Report Reviewer
for
Bill Champion
Program Manager
443.622.5067
bill.champion@bureauveritas.com

8. Appendices

- Appendix A: Photographic Record
- Appendix B: Site Plan(s)
- Appendix C: Pre-Survey Questionnaire(s)
- Appendix D: Accessibility Review and Photos
- Appendix E: Component Condition Report
- Appendix F: Replacement Reserves
- Appendix G: Equipment Inventory List

Appendix A:

Photographic Record

Photographic Overview



1 - FRONT ELEVATION



2 - LEFT ELEVATION



3 - REAR ELEVATION



4 - RIGHT ELEVATION



5 - MAIN ENTRANCE



6 - TYPICAL CLASSROOM


Photographic Overview



7 - LIBRARY



8 - CONFERENCE ROOM




9 - GYMNASIUM



10 - AUDITORIUM



11 - ELEVATOR



12 - TYPICAL HALLWAY

Photographic Overview



13 - BOILERS



14 - WATER HEATER



15 - MAIN SWITCHBOARD



16 - SECONDARY SWITCHBOARD



17 - TYPICAL TRANSFORMER



18 - FIRE ALARM PANEL

Photographic Overview




19 - TYPICAL FCU



20 - COOLING TOWER



21 - TYPICAL RTUS



22 - TYPICAL SPLIT SYSTEM UNIT



23 - TYPICAL EXHAUST FAN



24 - GENERATOR


Photographic Overview




25 - ASPHALT OVERVIEW




26 - PARKING LOT



27 - BASKETBALL PLAY AREA



28 - CONCRETE WALKWAY



29 - PLAYGROUND



30 - EXTERIOR LIGHTS

Appendix B:

Site Plan(s)

Site Plan



 BUREAU VERITAS	Project Number	Project Name	
	172559.25R000-127.354	Wayside Elementary School	
	Source	On-Site Date	
	Google	September 15, 2025	

Appendix C:

Pre-Survey Questionnaire(s)

BV FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

Building / Facility Name: Wayside Elementary School

Name of person completing form: Violetta

Title / Association w/ property: Maintenance

Length of time associated w/ property:

Date Completed: 9/15/2025

Phone Number:

Method of Completion: INTERVIEW - verbally completed during interview

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.


Data Overview		Response		
1	Year(s) constructed	Constructed 1969	Renovated 2017	
2	Building size in SF	93,453 SF		
3	Major Renovation/Rehabilitation		Year	Additional Detail
		Facade		
		Roof		
		Interiors		
		HVAC		
		Electrical		
		Site Pavement		
		Accessibility		
4	List other significant capital improvements (focus on recent years; provide approximate date).	Redid bathroom, changed bulbs to LED.		
5	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?			
6	Describe any on-going extremely problematic, historically chronic, or immediate facility needs.	Main lobby has sewer smell, DOAS HVAC will be fixed		

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

Question		Response				Comments
		Yes	No	Unk	NA	
7	Are there any problems with foundations or structures, like excessive settlement?		X			
8	Are there any wall, window, basement or roof leaks?		X			
9	Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality complaints?		X			
10	Are your elevators unreliable, with frequent service calls?		X			
11	Are there any plumbing leaks, water pressure, or clogging/backup issues?		X			
12	Have there been any leaks or pressure problems with natural gas, HVAC piping, or steam service?		X			
13	Are any areas of the facility inadequately heated, cooled or ventilated? Poorly insulated areas?	X				Get complaints but it's working generally, complain about humidity
14	Is the electrical service outdated, undersized, or problematic?		X			
15	Are there any problems or inadequacies with exterior lighting?		X			
16	Is site/parking drainage inadequate, with excessive ponding or other problems?		X			
17	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above?		X			
18	ADA: Has an accessibility study been previously performed? If so, when?				X	
19	ADA: Have any ADA improvements been made to the property since original construction? Describe.				X	
20	ADA: Has building management reported any accessibility-based complaints or litigation?				X	
21	Are any areas of the property leased to outside occupants?			X		



Signature of Assessor



Signature of POC

Appendix D:

Accessibility Review and Photos

Visual Survey - 2010 ADA Standards for Accessible Design

Property Name: Wayside Elementary School

BV Project Number: 172559.25R000-127.354

Facility History & Interview					
Question		Yes	No	Unk	Comments
1	Has an accessibility study been previously performed? If so, when?			X	
2	Have any ADA improvements been made to the property since original construction? Describe.			X	
3	Has building management reported any accessibility-based complaints or litigation?			X	

Wayside Elementary School: Accessibility Issues				
Category	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor Issues	None*
Parking				X
Exterior Accessible Route				X
Building Entrances				X
Interior Accessible Route				X
Elevators				X
Public Restrooms				X
Kitchens/Kitchenettes	NA			
Playgrounds & Swimming Pools				X
Other	NA			

**Be cognizant that if the "None" box is checked that does not guarantee full compliance; this study is limited in nature*

Wayside Elementary School: Photographic Overview



OVERVIEW OF ACCESSIBLE PARKING AREA



CLOSE-UP OF STALL



ACCESSIBLE PATH



CURB CUT



MAIN ENTRANCE




DOOR HARDWARE

Wayside Elementary School: Photographic Overview



ACCESSIBLE INTERIOR PATH




DOOR HARDWARE



LOBBY LOOKING AT CABS (WITH DOORS OPEN)



IN-CAB CONTROLS



TOILET STALL OVERVIEW



SINK, FAUCET HANDLES, AND ACCESSORIES

Wayside Elementary School: Photographic Overview



OVERVIEW OF PLAYGROUND



ACCESSIBLE ROUTE TO PLAYGROUND

Appendix E:

Component Condition Report

Component Condition Report | Wayside Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
A4010	Throughout Building	Good	Foundation, Concrete, Standard w/ Integral Perimeter Footings, w/ Integral Perimeter Footings	93,453 SF	67	9758154
B1010	Throughout Building	Good	Structural Framing, Masonry (CMU) Bearing Walls, 1-2 Story Building, 1-2 Story Building	93,453 SF	67	9758034
Facade						
B2020	Building Exterior	Good	Glazing, any type by SF	5,000 SF	22	9758063
B2050	Building Exterior	Fair	Overhead/Dock Door, Aluminum, 12'x12' (144 SF)	2	3	9758066
B2050	Building Exterior	Good	Exterior Door, Steel, Standard	14	22	9758053
Roofing						
B3010	Roof	Fair	Roofing, Modified Bitumen	68,000 SF	9	9805584
Interiors						
C1030	Throughout Building	Fair	Interior Door, Wood, Solid-Core	150	23	9758065
C1070	Throughout Building	Fair	Suspended Ceilings, Acoustical Tile (ACT)	85,453 SF	14	9758126
C2010	Throughout Building	Fair	Wall Finishes, any surface, Prep & Paint	130,180 SF	5	9758103
C2030	Gymnasium	Good	Flooring, Wood, Sports, Refinish	5,000 SF	7	9758139
C2030	Throughout Building	Fair	Flooring, Carpet, Commercial Standard	17,700 SF	5	9758092
C2030	Throughout Building	Fair	Flooring, Vinyl Tile (VCT)	64,100 SF	7	9758035
Conveying						
D1010	Elevator Shafts/Utility	Good	Passenger Elevator, Hydraulic, 2 Floors, Renovate	1	22	9758038
D1010	Elevator Shafts/Utility	Fair	Elevator Controls, Automatic, 1 Car	1	3	9758115
D1010	Elevator Shafts/Utility	Fair	Elevator Cab Finishes, Standard	1	7	9758072
Plumbing						
D2010	Boiler Room	Good	Water Heater, Gas, Commercial (400 MBH)	1	18	9758152

Component Condition Report | Wayside Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D2010	Boiler Room	Good	Backflow Preventer, Domestic Water	1	20	9758151
D2010	Throughout Building	Good	Plumbing System, Supply & Sanitary, Low Density (excludes fixtures)	93,453 SF	32	9758055
D2010	Boiler Room	Fair	Backflow Preventer, Domestic Water	1	15	9758161
D2010	Restrooms	Fair	Urinal, Standard	20	15	9758124
D2010	Restrooms	Fair	Toilet, Commercial Water Closet	70	15	9758043
D2010	Restrooms	Fair	Sink/Lavatory, Wall-Hung, Enameled Steel	60	12	9758077
HVAC						
D3020	Boiler Room	Good	Boiler, Gas, HVAC [BOILER-1]	1	22	9758082
D3020	Boiler Room	Good	Boiler, Gas, HVAC [BOILER-2]	1	22	9758159
D3020	Boiler Room	Good	Heat Exchanger, Plate & Frame, HVAC [HX-1]	1	27	9758095
D3020	Boiler Room	Fair	Unit Heater, Electric [EUH-6]	1	12	9758060
D3020	Boiler Room	Fair	Unit Heater, Electric [EUH-7]	1	12	9758033
D3030	Roof	Fair	Split System Ductless, Single Zone	1	7	9758073
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-10]	1	5	9758100
D3030	Roof	Good	Cooling Tower, (Typical) Open Circuit [CT-1]	1	17	9758157
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-2]	1	6	9758080
D3030	Roof	Fair	Heat Pump, Var Refrig Vol (VRV) [HP-1]	1	5	9758116
D3030	Roof	Fair	Split System Ductless, Single Zone [DSS-2]	1	3	9758090
D3030	Roof	Fair	Split System Ductless, Single Zone [DSS-1]	1	3	9758081
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-9]	1	5	9758118
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-6]	1	6	9758108
D3030	Roof	Fair	Heat Pump, Var Refrig Vol (VRV) [HP-3]	1	4	9758111
D3030	Roof	Fair	Heat Pump, Var Refrig Vol (VRV) [AC-8]	1	6	9758042
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-5]	1	7	9758130

Component Condition Report | Wayside Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-13]	1	8	9758122
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-3]	1	5	9758120
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-7]	1	5	9758032
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-11]	1	6	9758113
D3030	Throughout Building	Fair	Split System, Fan Coil Unit, DX	10	7	9758071
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-1]	1	7	9758156
D3030	Roof	Fair	Heat Pump, Var Refrig Vol (VRV) [HP-4]	1	5	9758037
D3030	Roof	Fair	Split System Ductless, Single Zone [AC-12]	1	7	9758153
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [HV-1]	1	12	9758107
D3050	Boiler Room	Good	Pump, Distribution, HVAC Heating Water [P-2]	1	17	9758148
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [DOAS-3]	1	12	9758163
D3050	Throughout Building	Fair	Fan Coil Unit, Hydronic Terminal	30	12	9758098
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [DOAS-4]	1	12	9758123
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [DOAS-1]	1	12	9758101
D3050	Boiler Room	Good	Pump, Distribution, HVAC Heating Water [P-3]	1	17	9758070
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [DOAS-5]	1	12	9758058
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [DOAS-2]	1	12	9758104
D3050	Boiler Room	Good	Pump, Distribution, HVAC Heating Water [P-1]	1	17	9758079
D3050	Building Exterior	Fair	Air Handler, Exterior AHU [ERU-1]	1	3	9758110
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [ERU-1]	1	12	9758162
D3050	Throughout Building	Good	HVAC System, Ductwork, Medium Density	93,453 SF	22	9758051
D3050	Roof	Fair	Packaged Unit, RTU, Pad or Roof-Mounted [DOAS-6]	1	12	9758138
D3050	Boiler Room	Good	Pump, Distribution, HVAC Heating Water [P-4]	1	17	9758145
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 24" Damper [RV-3]	1	5	9758144

Component Condition Report | Wayside Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 24" Damper [EF-2]	1	12	9758128
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper [PRV-6]	1	5	9758084
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 28" Damper [PRV-4]	1	5	9758046
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper [PRV-7]	1	15	9758050
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 24" Damper [PRV-5]	1	12	9758068
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 12" Damper [PRV-1]	1	5	9758114
D3060	Kitchen	Fair	Supplemental Components, Air Curtain, 5' Wide Non-Heated	1	12	9758137
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 28" Damper [RV-1]	1	10	9758087
D3060	Roof	Fair	Exhaust Fan, Roof or Wall-Mounted, 42" Damper [SF-1]	1	13	9758117
D3060	Hallways & Common Areas	Fair	Supplemental Components, Air Curtain, 5' Wide Non-Heated	1	12	9758078
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 28" Damper [RV-2]	1	10	9758089
D3060	Roof	Fair	Exhaust Fan, Roof or Wall-Mounted, 42" Damper [SF-2]	1	13	9758040
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 24" Damper [EF-1]	1	12	9758047
Fire Protection						
D4010	Throughout Building	Good	Fire Suppression System, Existing Sprinkler Heads, by SF	93,453 SF	17	9758106
D4010	Boiler Room	Fair	Backflow Preventer, Fire Suppression	1	10	9758112
D4010	Boiler Room	Fair	Backflow Preventer, Fire Suppression	1	10	9758147
Electrical						
D5010	FACP Room	Fair	Automatic Transfer Switch, ATS	1	15	9758088
D5010	FACP Room	Fair	Automatic Transfer Switch, ATS	1	15	9758085
D5020	FACP Room	Good	Switchboard, 277/480 V	1	32	9758067
D5020	FACP Room	Good	Secondary Transformer, Dry, Stepdown	1	21	9758102
D5020	Intermediate Book Closet Electrical Room	Fair	Secondary Transformer, Dry, Stepdown	1	15	9758155
D5020	FACP Room	Good	Distribution Panel, 277/480 V	1	22	9758099

Component Condition Report | Wayside Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D5020	Exterior Electrical Room	Fair	Distribution Panel, 120/208 V	1	12	9758041
D5020	FACP Room	Good	Secondary Transformer, Dry, Stepdown	1	21	9758135
D5020	Exterior Electrical Room	Fair	Secondary Transformer, Dry, Stepdown	1	12	9758105
D5020	Electrical Room	Good	Secondary Transformer, Dry, Stepdown	1	21	9758127
D5020	Exterior Electrical Room	Fair	Distribution Panel, 120/208 V	1	12	9758160
D5020	FACP Room	Good	Secondary Transformer, Dry, Stepdown	1	21	9758048
D5020	Electrical Room 214	Good	Secondary Transformer, Dry, Stepdown	1	21	9758056
D5020	FACP Room	Good	Distribution Panel, 277/480 V	1	22	9758044
D5020	Exterior Electrical Room	Fair	Distribution Panel, 120/208 V	1	12	9758059
D5020	Electrical Room	Good	Secondary Transformer, Dry, Stepdown	1	21	9758140
D5020	Electrical Room 225	Good	Secondary Transformer, Dry, Stepdown	1	21	9758133
D5020	FACP Room	Good	Secondary Transformer, Dry, Stepdown	1	21	9758031
D5020	Exterior Electrical Room	Fair	Switchboard, 277/480 V	1	23	9758136
D5020	Electrical Room 225	Good	Distribution Panel, 277/480 V	1	22	9758134
D5020	Electrical Room 225	Good	Secondary Transformer, Dry, Stepdown	1	21	9758146
D5020	FACP Room	Good	Secondary Transformer, Dry, Stepdown	1	21	9758096
D5020	Electrical Room 214	Good	Distribution Panel, 277/480 V	1	22	9758131
D5020	Electrical Room 225	Good	Distribution Panel, 277/480 V	1	22	9758083
D5030	Boiler Room	Fair	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	1	12	9758143
D5030	Boiler Room	Fair	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	1	12	9758061
D5030	Throughout Building	Good	Electrical System, Wiring & Switches, Average or Low Density/Complexity	93,453 SF	32	9758094
D5040	Building Exterior	Fair	Exterior Light, any type, w/ LED Replacement	30	12	9758158
D5040	Throughout Building	Good	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures	93,453 SF	19	9758075
Fire Alarm & Electronic Systems						

Component Condition Report | Wayside Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D6060	Throughout Building	Fair	Intercom/PA System, Public Address Upgrade, Facility-Wide	93,453 SF	12	9758049
D7030	Throughout Building	Good	Security/Surveillance System, Full System Upgrade, Average Density	93,453 SF	11	9758132
D7050	FACP Room	Fair	Fire Alarm Panel, Fully Addressable	1	8	9758109
D7050	Throughout Building	Fair	Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install	93,453 SF	12	9758069
D8010	Throughout Building	Fair	BAS/HVAC Controls, Basic System or Legacy Upgrades, Upgrade/Install	93,453 SF	7	9758164
Equipment & Furnishings						
E1030	Kitchen	Fair	Foodservice Equipment, Convection Oven, Double	1	5	9758039
E1030	Kitchen	Good	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer	1	10	9758086
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	7	9758119
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	8	9758125
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	7	9758093
E1030	Roof	Fair	Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer	1	5	9758149
E1030	Kitchen	Good	Foodservice Equipment, Walk-In, Freezer	1	15	9758129
E1030	Roof	Fair	Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer	1	5	9758074
E1030	Kitchen	Fair	Foodservice Equipment, Steamer, Freestanding	1	6	9758057
E1030	Kitchen	Fair	Foodservice Equipment, Refrigerator, 1-Door Reach-In	1	7	9758062
E1030	Kitchen	Fair	Foodservice Equipment, Exhaust Hood, 3 to 6 LF	1	8	9758052
E1030	Kitchen	Good	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer	1	10	9758064
E1030	Kitchen	Good	Foodservice Equipment, Walk-In, Refrigerator	1	15	9758045
E1030	Kitchen	Fair	Foodservice Equipment, Commercial Kitchen, 3-Bowl	1	15	9758036
E1070	Gymnasium	Fair	Basketball Backboard, Wall-Mounted, Fixed, Fixed	6	5	9758142

Component Condition Report | Wayside Elementary School

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						

Component Condition Report | Wayside Elementary School

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B2010	Building exterior	Fair	Exterior Walls, Brick/Masonry/Stone, Clean & Seal, Maintain	30,000 SF	12	9829769

Component Condition Report | Wayside Elementary School / Site

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Electrical						
D5010	Building Exterior	Good	Generator, Diesel	1	17	9766755
Pedestrian Plazas & Walkways						
G2020	Site Parking Areas	Fair	Parking Lots, Pavement, Asphalt, Mill & Overlay	50,000 SF	17	9766754
G2020	Site Parking Areas	Fair	Parking Lots, Pavement, Asphalt, Seal & Stripe	50,000 SF	3	9766758
Athletic, Recreational & Playfield Areas						
G2050	Site Sports Fields & Courts	Fair	Sports Apparatus, Basketball, Backboard/Rim/Pole	2	12	9766759
G2050	Site Playground Areas	Fair	Playground Surfaces, Chips Wood, 6" Depth	2,000 SF	3	9766756
G2050	Site Playground Areas	Fair	Play Structure, Multipurpose, Medium	2	5	9766757
Sitework						
G2060	Site	Fair	Fences & Gates, Fence, Chain Link 4'	300 LF	16	9806123
G4050	Site	Fair	Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, Replace/Install	6	11	9766753

Appendix F: Replacement Reserves

Replacement Reserves Report



10/16/2025

Location	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Total Escalated Estimate
Wayside Elementary School	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,557	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,557
Wayside Elementary School / Main Building	\$0	\$0	\$0	\$155,277	\$49,522	\$543,908	\$62,449	\$790,480	\$32,176	\$887,246	\$40,855	\$258,722	\$1,494,848	\$32,308	\$452,394	\$941,168	\$16,849	\$378,989	\$53,797	\$896,506	\$184,223	\$7,271,717
Wayside Elementary School / Site	\$0	\$0	\$0	\$28,957	\$0	\$46,371	\$0	\$0	\$33,569	\$0	\$0	\$33,222	\$13,545	\$38,916	\$0	\$0	\$8,665	\$431,393	\$45,114	\$0	\$0	\$679,753
Grand Total	\$0	\$0	\$0	\$184,234	\$49,522	\$590,279	\$62,449	\$790,480	\$65,745	\$887,246	\$40,855	\$291,943	\$1,587,950	\$71,224	\$452,394	\$941,168	\$25,515	\$810,382	\$98,911	\$896,506	\$184,223	\$8,031,028

Wayside Elementary School

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate				
B2010	Building exterior	9829769	Exterior Walls, Brick/Masonry/Stone, Clean & Seal, Maintain	20	8	12	30000	SF	\$1.86	\$55,800													\$55,800									\$55,800				
Totals, Unescalated											\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,800	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,800	
Totals, Escalated (3.0% inflation, compounded annually)											\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,557	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,557

Wayside Elementary School / Main Building

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate
B2050	Building Exterior	9758066	Overhead/Dock Door, Aluminum, 12'x12' (144 SF), Replace	30	27	3	2	EA	\$4,400.00	\$8,800																						\$8,800
B3010	Roof	9805584	Roofing, Modified Bitumen, Replace	20	11	9	68000	SF	\$10.00	\$680,000														\$680,000								\$680,000
C1070	Throughout Building	9758126	Suspended Ceilings, Acoustical Tile (ACT), Replace	25	11	14	85453	SF	\$3.50	\$299,086																		\$299,086				\$299,086
C2010	Throughout Building	9758103	Wall Finishes, any surface, Prep & Paint	10	5	5	130180	SF	\$1.50	\$195,270								\$195,270											\$195,270			\$390,540
C2030	Throughout Building	9758035	Flooring, Vinyl Tile (VCT), Replace	15	8	7	64100	SF	\$5.00	\$320,500										\$320,500												\$320,500
C2030	Throughout Building	9758092	Flooring, Carpet, Commercial Standard, Replace	10	5	5	17700	SF	\$7.50	\$132,750									\$132,750									\$132,750				\$265,500
C2030	Gymnasium	9758139	Flooring, Wood, Sports, Refinish	10	3	7	5000	SF	\$5.00	\$25,000											\$25,000								\$25,000			\$50,000
D1010	Elevator Shafts/Utility	9758115	Elevator Controls, Automatic, 1 Car, Replace	20	17	3	1	EA	\$5,000.00	\$5,000							\$5,000															\$5,000
D1010	Elevator Shafts/Utility	9758072	Elevator Cab Finishes, Standard, Replace	15	8	7	1	EA	\$9,000.00	\$9,000											\$9,000											\$9,000
D2010	Boiler Room	9758152	Water Heater, Gas, Commercial (400 MBH), Replace	20	2	18	1	EA	\$22,000.00	\$22,000																				\$22,000		\$22,000
D2010	Boiler Room	9758161	Backflow Preventer, Domestic Water, Replace	30	15	15	1	EA	\$3,200.00	\$3,200																				\$3,200		\$3,200
D2010	Boiler Room	9758151	Backflow Preventer, Domestic Water, Replace	30	10	20	1	EA	\$1,400.00	\$1,400																					\$1,400	\$1,400
D2010	Restrooms	9758077	Sink/Lavatory, Wall-Hung, Enameled Steel, Replace	30	18	12	60	EA	\$1,700.00	\$102,000																	\$102,000					\$102,000
D2010	Restrooms	9758124	Urinal, Standard, Replace	30	15	15	20	EA	\$1,100.00	\$22,000																				\$22,000		\$22,000
D2010	Restrooms	9758043	Toilet, Commercial Water Closet, Replace	30	15	15	70	EA	\$1,300.00	\$91,000																				\$91,000		\$91,000
D3020	Boiler Room	9758060	Unit Heater, Electric, Replace	20	8	12	1	EA	\$2,200.00	\$2,200																	\$2,200					\$2,200
D3020	Boiler Room	9758033	Unit Heater, Electric, Replace	20	8	12	1	EA	\$2,200.00	\$2,200																	\$2,200					\$2,200
D3030	Roof	9758157	Cooling Tower, (Typical) Open Circuit, Replace	25	8	17	1	EA	\$46,700.00	\$46,700																				\$46,700		\$46,700
D3030	Roof	9758090	Split System Ductless, Single Zone, Replace	15	12	3	1	EA	\$4,800.00	\$4,800							\$4,800													\$4,800		\$9,600
D3030	Roof	9758081	Split System Ductless, Single Zone, Replace	15	12	3	1	EA	\$4,800.00	\$4,800							\$4,800													\$4,800		\$9,600
D3030	Roof	9758111	Heat Pump, Var Refrig Vol (VRV), Replace	15	11	4	1	EA	\$44,000.00	\$44,000								\$44,000													\$44,000	\$88,000
D3030	Roof	9758100	Split System Ductless, Single Zone, Replace	15	10	5	1	EA	\$3,500.00	\$3,500									\$3,500												\$3,500	\$7,000
D3030	Roof	9758116	Heat Pump, Var Refrig Vol (VRV), Replace	15	10	5	1	EA	\$44,000.00	\$44,000									\$44,000												\$44,000	\$88,000
D3030	Roof	9758118	Split System Ductless, Single Zone, Replace	15	10	5	1	EA	\$3,500.00	\$3,500									\$3,500												\$3,500	\$7,000
D3030	Roof	9758120	Split System Ductless, Single Zone, Replace	15	10	5	1	EA	\$3,500.00	\$3,500									\$3,500												\$3,500	\$7,000
D3030	Roof	9758032	Split System Ductless, Single Zone, Replace	15	10	5	1	EA	\$3,500.00	\$3,500									\$3,500												\$3,500	\$7,000
D3030	Roof	9758037	Heat Pump, Var Refrig Vol (VRV), Replace	15	10	5	1	EA	\$30,000.00	\$30,000									\$30,000												\$30,000	\$60,000
D3030	Roof	9758080	Split System Ductless, Single Zone, Replace	15	9	6	1	EA	\$3,500.00	\$3,500										\$3,500												\$3,500
D3030	Roof	9758108	Split System Ductless, Single Zone, Replace	15	9	6	1	EA	\$3,500.00	\$3,500										\$3,500												\$3,500
D3030	Roof	9758042	Heat Pump, Var Refrig Vol (VRV), Replace	15	9	6	1	EA	\$30,000.00	\$30,000										\$30,000												\$30,000
D3030	Roof	9758113	Split System Ductless, Single Zone, Replace	15	9	6	1	EA	\$4,800.00	\$4,800										\$4,800												\$4,800
D3030	Roof	9758073	Split System Ductless, Single Zone, Replace	15	8	7	1	EA	\$4,800.00	\$4,800										\$4,800												\$4,800
D3030	Roof	9758130	Split System Ductless, Single Zone, Replace	15	8	7	1	EA	\$3,500.00	\$3,500										\$3,500												\$3,500
D3030	Throughout Building	9758071	Split System, Fan Coil Unit, DX, Replace	15	8	7	10	EA	\$3,000.00	\$30,000										\$30,000												\$30,000
D3030	Roof	9758156	Split System Ductless, Single Zone, Replace	15	8	7	1	EA	\$3,500.00	\$3,500										\$3,500												\$3,500
D3030	Roof	9758153	Split System Ductless, Single Zone, Replace	15	8	7	1	EA	\$4,800.00	\$4,800										\$4,800												\$4,800
D3030	Roof	9758122	Split System Ductless, Single Zone, Replace	15	7	8	1	EA	\$3,500.00	\$3,500														\$3,500								\$3,500
D3050	Boiler Room	9758148	Pump, Distribution, HVAC Heating Water, Replace	25	8	17	1	EA	\$22,000.00	\$22,000																				\$22,000		\$22,000

Replacement Reserves Report



10/16/2025

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate
D3050	Boiler Room	9758070	Pump, Distribution, HVAC Heating Water, Replace	25	8	17	1	EA	\$6,800.00	\$6,800																		\$6,800				\$6,800
D3050	Boiler Room	9758079	Pump, Distribution, HVAC Heating Water, Replace	25	8	17	1	EA	\$22,000.00	\$22,000																		\$22,000				\$22,000
D3050	Boiler Room	9758145	Pump, Distribution, HVAC Heating Water, Replace	25	8	17	1	EA	\$6,800.00	\$6,800																		\$6,800				\$6,800
D3050	Building Exterior	9758110	Air Handler, Exterior AHU, Replace	20	17	3	1	EA	\$118,700.00	\$118,700				\$118,700																		\$118,700
D3050	Roof	9758107	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$75,000.00	\$75,000													\$75,000									\$75,000
D3050	Roof	9758163	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$40,000.00	\$40,000													\$40,000									\$40,000
D3050	Throughout Building	9758098	Fan Coil Unit, Hydronic Terminal, Replace	20	8	12	30	EA	\$1,670.00	\$50,100													\$50,100									\$50,100
D3050	Roof	9758123	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$75,000.00	\$75,000													\$75,000									\$75,000
D3050	Roof	9758101	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$15,000.00	\$15,000													\$15,000									\$15,000
D3050	Roof	9758058	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$40,000.00	\$40,000													\$40,000									\$40,000
D3050	Roof	9758104	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$15,000.00	\$15,000													\$15,000									\$15,000
D3050	Roof	9758162	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$75,000.00	\$75,000													\$75,000									\$75,000
D3050	Roof	9758138	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	8	12	1	EA	\$20,000.00	\$20,000													\$20,000									\$20,000
D3060	Roof	9758144	Exhaust Fan, Centrifugal, 24" Damper, Replace	25	20	5	1	EA	\$3,000.00	\$3,000						\$3,000																\$3,000
D3060	Roof	9758084	Exhaust Fan, Centrifugal, 16" Damper, Replace	25	20	5	1	EA	\$2,400.00	\$2,400						\$2,400																\$2,400
D3060	Roof	9758046	Exhaust Fan, Centrifugal, 28" Damper, Replace	25	20	5	1	EA	\$4,000.00	\$4,000						\$4,000																\$4,000
D3060	Roof	9758114	Exhaust Fan, Centrifugal, 12" Damper, Replace	25	20	5	1	EA	\$1,400.00	\$1,400						\$1,400																\$1,400
D3060	Roof	9758087	Exhaust Fan, Centrifugal, 28" Damper, Replace	25	15	10	1	EA	\$4,000.00	\$4,000											\$4,000											\$4,000
D3060	Roof	9758089	Exhaust Fan, Centrifugal, 28" Damper, Replace	25	15	10	1	EA	\$4,000.00	\$4,000											\$4,000											\$4,000
D3060	Roof	9758128	Exhaust Fan, Centrifugal, 24" Damper, Replace	25	13	12	1	EA	\$3,000.00	\$3,000													\$3,000									\$3,000
D3060	Roof	9758068	Exhaust Fan, Centrifugal, 24" Damper, Replace	25	13	12	1	EA	\$3,000.00	\$3,000													\$3,000									\$3,000
D3060	Roof	9758047	Exhaust Fan, Centrifugal, 24" Damper, Replace	25	13	12	1	EA	\$3,000.00	\$3,000													\$3,000									\$3,000
D3060	Roof	9758117	Exhaust Fan, Roof or Wall-Mounted, 42" Damper, Replace	20	7	13	1	EA	\$11,000.00	\$11,000														\$11,000								\$11,000
D3060	Roof	9758040	Exhaust Fan, Roof or Wall-Mounted, 42" Damper, Replace	20	7	13	1	EA	\$11,000.00	\$11,000														\$11,000								\$11,000
D3060	Roof	9758050	Exhaust Fan, Centrifugal, 16" Damper, Replace	25	10	15	1	EA	\$2,400.00	\$2,400																\$2,400						\$2,400
D3060	Kitchen	9758137	Supplemental Components, Air Curtain, 5' Wide Non-Heated, Replace	20	8	12	1	EA	\$1,500.00	\$1,500												\$1,500										\$1,500
D3060	Hallways & Common Areas	9758078	Supplemental Components, Air Curtain, 5' Wide Non-Heated, Replace	20	8	12	1	EA	\$1,500.00	\$1,500												\$1,500										\$1,500
D4010	Boiler Room	9758112	Backflow Preventer, Fire Suppression, Replace	30	20	10	1	EA	\$6,600.00	\$6,600											\$6,600											\$6,600
D4010	Boiler Room	9758147	Backflow Preventer, Fire Suppression, Replace	30	20	10	1	EA	\$6,600.00	\$6,600											\$6,600											\$6,600
D4010	Throughout Building	9758106	Fire Suppression System, Existing Sprinkler Heads, by SF, Replace	25	8	17	93453	SF	\$1.07	\$99,995																		\$99,995				\$99,995
D5010	FACP Room	9758088	Automatic Transfer Switch, ATS, Replace	25	10	15	1	EA	\$50,000.00	\$50,000																\$50,000						\$50,000
D5010	FACP Room	9758085	Automatic Transfer Switch, ATS, Replace	25	10	15	1	EA	\$50,000.00	\$50,000																\$50,000						\$50,000
D5020	Exterior Electrical Room	9758105	Secondary Transformer, Dry, Stepdown, Replace	30	18	12	1	EA	\$25,000.00	\$25,000												\$25,000										\$25,000
D5020	Intermediate Book Closet Electrical Room	9758155	Secondary Transformer, Dry, Stepdown, Replace	30	15	15	1	EA	\$6,700.00	\$6,700																\$6,700						\$6,700
D5020	Exterior Electrical Room	9758041	Distribution Panel, 120/208 V, Replace	30	18	12	1	EA	\$8,000.00	\$8,000												\$8,000										\$8,000
D5020	Exterior Electrical Room	9758160	Distribution Panel, 120/208 V, Replace	30	18	12	1	EA	\$8,000.00	\$8,000												\$8,000										\$8,000
D5020	Exterior Electrical Room	9758059	Distribution Panel, 120/208 V, Replace	30	18	12	1	EA	\$8,000.00	\$8,000												\$8,000										\$8,000
D5030	Boiler Room	9758143	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	20	8	12	1	EA	\$14,700.00	\$14,700												\$14,700										\$14,700
D5030	Boiler Room	9758061	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	20	8	12	1	EA	\$14,700.00	\$14,700												\$14,700										\$14,700
D5040	Building Exterior	9758158	Exterior Light, any type, w/ LED Replacement, Replace	20	8	12	30	EA	\$400.00	\$12,000												\$12,000										\$12,000
D5040	Throughout Building	9758075	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures, Replace	20	1	19	93453	SF	\$5.00	\$467,265																				\$467,265		\$467,265
D6060	Throughout Building	9758049	Intercom/PA System, Public Address Upgrade, Facility-Wide, Replace	20	8	12	93453	SF	\$1.65	\$154,197													\$154,197									\$154,197
D7030	Throughout Building	9758132	Security/Surveillance System, Full System Upgrade, Average Density, Replace	15	4	11	93453	SF	\$2.00	\$186,906											\$186,906											\$186,906
D7050	FACP Room	9758109	Fire Alarm Panel, Fully Addressable, Replace	15	7	8	1	EA	\$15,000.00	\$15,000								\$15,000														\$15,000
D7050	Throughout Building	9758069	Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install	20	8	12	93453	SF	\$3.00	\$280,359												\$280,359										\$280,359
D8010	Throughout Building	9758164	BAS/HVAC Controls, Basic System or Legacy Upgrades, Upgrade/Install	15	8	7	93453	SF	\$2.50	\$233,633								\$233,633														\$233,633
E1030	Kitchen	9758039	Foodservice Equipment, Convection Oven, Double, Replace	10	5	5	1	EA	\$8,280.00	\$8,280						\$8,280									\$8,280							\$16,560
E1030	Roof	9758149	Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer, Replace	15	10	5	1	EA	\$6,300.00	\$6,300						\$6,300														\$6,300		\$12,600
E1030	Roof	9758074	Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer, Replace	15	10	5	1	EA	\$6,300.00	\$6,300						\$6,300														\$6,300		\$12,600
E1030	Kitchen	9758057	Foodservice Equipment, Steamer, Freestanding, Replace	10	4	6	1	EA	\$10,500.00	\$10,500							\$10,500									\$10,500						\$21,000
E1030	Kitchen	9758119	Foodservice Equipment, Dairy Cooler/Wells, Replace	15	8	7	1	EA	\$3,600.00	\$3,600								\$3,600														\$3,600

Replacement Reserves Report



10/16/2025

Uniformal Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate
E1030	Kitchen	9758093	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	8	7	1	EA	\$1,700.00	\$1,700								\$1,700														\$1,700
E1030	Kitchen	9758062	Foodservice Equipment, Refrigerator, 1-Door Reach-In, Replace	15	8	7	1	EA	\$2,700.00	\$2,700								\$2,700														\$2,700
E1030	Kitchen	9758125	Foodservice Equipment, Dairy Cooler/Wells, Replace	15	7	8	1	EA	\$3,600.00	\$3,600									\$3,600													\$3,600
E1030	Kitchen	9758052	Foodservice Equipment, Exhaust Hood, 3 to 6 LF, Replace	15	7	8	1	EA	\$3,300.00	\$3,300									\$3,300													\$3,300
E1030	Kitchen	9758086	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer, Replace	15	5	10	1	EA	\$4,600.00	\$4,600											\$4,600											\$4,600
E1030	Kitchen	9758064	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer, Replace	15	5	10	1	EA	\$4,600.00	\$4,600											\$4,600											\$4,600
E1030	Kitchen	9758129	Foodservice Equipment, Walk-In, Freezer, Replace	20	5	15	1	EA	\$25,000.00	\$25,000																\$25,000						\$25,000
E1030	Kitchen	9758045	Foodservice Equipment, Walk-In, Refrigerator, Replace	20	5	15	1	EA	\$15,000.00	\$15,000																\$15,000						\$15,000
E1030	Kitchen	9758036	Foodservice Equipment, Commercial Kitchen, 3-Bowl, Replace	30	15	15	1	EA	\$2,500.00	\$2,500																\$2,500						\$2,500
E1070	Gymnasium	9758142	Basketball Backboard, Wall-Mounted, Fixed, Fixed	30	25	5	6	EA	\$3,580.00	\$21,480						\$21,480																\$21,480
Totals, Unescalated											\$0	\$0	\$0	\$142,100	\$44,000	\$469,180	\$52,300	\$642,733	\$25,400	\$680,000	\$30,400	\$186,906	\$1,048,456	\$22,000	\$299,086	\$604,100	\$10,500	\$229,295	\$31,600	\$511,265	\$102,000	\$5,131,320
Totals, Escalated (3.0% inflation, compounded annually)											\$0	\$0	\$0	\$155,277	\$49,522	\$543,908	\$62,449	\$790,480	\$32,176	\$887,246	\$40,855	\$258,722	\$1,494,848	\$32,308	\$452,394	\$941,168	\$16,849	\$378,989	\$53,797	\$896,506	\$184,223	\$7,271,717

Wayside Elementary School / Site

Uniformal Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate
D5010	Building Exterior	9766755	Generator, Diesel, Replace	25	8	17	1	EA	\$86,000.00	\$86,000																	\$86,000					\$86,000
G2020	Site Parking Areas	9766758	Parking Lots, Pavement, Asphalt, Seal & Stripe	5	2	3	50000	SF	\$0.45	\$22,500				\$22,500					\$22,500					\$22,500				\$22,500				\$90,000
G2020	Site Parking Areas	9766754	Parking Lots, Pavement, Asphalt, Mill & Overlay	25	8	17	50000	SF	\$3.50	\$175,000																\$175,000						\$175,000
G2050	Site Sports Fields & Courts	9766759	Sports Apparatus, Basketball, Backboard/Rim/Pole, Replace	25	13	12	2	EA	\$4,750.00	\$9,500												\$9,500										\$9,500
G2050	Site Playground Areas	9766756	Playground Surfaces, Chips Wood, 6" Depth, Replace	5	2	3	2000	SF	\$2.00	\$4,000				\$4,000				\$4,000					\$4,000					\$4,000				\$16,000
G2050	Site Playground Areas	9766757	Play Structure, Multipurpose, Medium, Replace	20	15	5	2	EA	\$20,000.00	\$40,000					\$40,000																	\$40,000
G2060	Site	9806123	Fences & Gates, Fence, Chain Link 4', Replace	40	24	16	300	LF	\$18.00	\$5,400															\$5,400							\$5,400
G4050	Site	9766753	Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, Replace/Install	20	9	11	6	EA	\$4,000.00	\$24,000											\$24,000											\$24,000
Totals, Unescalated											\$0	\$0	\$0	\$26,500	\$0	\$40,000	\$0	\$0	\$26,500	\$0	\$0	\$24,000	\$9,500	\$26,500	\$0	\$0	\$5,400	\$261,000	\$26,500	\$0	\$0	\$445,900
Totals, Escalated (3.0% inflation, compounded annually)											\$0	\$0	\$0	\$28,957	\$0	\$46,371	\$0	\$0	\$33,569	\$0	\$0	\$33,222	\$13,545	\$38,916	\$0	\$0	\$8,665	\$431,393	\$45,114	\$0	\$0	\$679,753

* Markup has been included in unit costs.

Appendix G:

Equipment Inventory List

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D10 Conveying													
1	9758115	D1010	Elevator Controls	Automatic, 1 Car		Wayside Elementary School / Main Building	Elevator Shafts/Utility	Schindler Elevator Corporation	NA	NA	2008		
2	9758038	D1010	Passenger Elevator	Hydraulic, 2 Floors	1500 - 2500 LB	Wayside Elementary School / Main Building	Elevator Shafts/Utility	NA	NA	NA	2017		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D20 Plumbing													
1	9758152	D2010	Water Heater	Gas, Commercial (400 MBH)	119 GAL	Wayside Elementary School / Main Building	Boiler Room	State	SUF-119-400-NEA 300	2343136312151	2023		
2	9758151	D2010	Backflow Preventer	Domestic Water	1 IN	Wayside Elementary School / Main Building	Boiler Room	Watts	LF00SM2QT	310516			
3	9758161	D2010	Backflow Preventer	Domestic Water	1.5 IN	Wayside Elementary School / Main Building	Boiler Room	Watts	LF008M2QT	030149			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D30 HVAC													
1	9758082	D3020	Boiler [BOILER-1]	Gas, HVAC	1400 MBH	Wayside Elementary School / Main Building	Boiler Room	Fulton	EDR-1500	4089-HFTC	2017		
2	9758159	D3020	Boiler [BOILER-2]	Gas, HVAC	1400 MBH	Wayside Elementary School / Main Building	Boiler Room	Fulton	EDR-1500	4106-HFTC	2017		
3	9758095	D3020	Heat Exchanger [HX-1]	Plate & Frame, HVAC	41 - 75 GPM	Wayside Elementary School / Main Building	Boiler Room	Boland	AQ6-FG	30116-99986	2017		
4	9758060	D3020	Unit Heater [EUH-6]	Electric	5 kW	Wayside Elementary School / Main Building	Boiler Room	TPI Corp	PSP5105CA1N	NA	2017		
5	9758033	D3020	Unit Heater [EUH-7]	Electric	7.5 kW	Wayside Elementary School / Main Building	Boiler Room	TPI Corp	P3P5107CA1N	NA	2017		
6	9758157	D3030	Cooling Tower [CT-1]	(Typical) Open Circuit	112 TON	Wayside Elementary School / Main Building	Roof	Evapco	UT 112-812L	16-781178	2017		
7	9758042	D3030	Heat Pump [AC-8]	Var Refrig Vol (VRV)	6 TON	Wayside Elementary School / Main Building	Roof	Daikin Industries	PUZ-A24NHA6	5ZU03331A	2016		
8	9758116	D3030	Heat Pump [HP-1]	Var Refrig Vol (VRV)	12 TON	Wayside Elementary School / Main Building	Roof	Daikin Industries	Illegible	Illegible			
9	9758111	D3030	Heat Pump [HP-3]	Var Refrig Vol (VRV)	10 TON	Wayside Elementary School / Main Building	Roof	Daikin Industries	Illegible	Illegible			
10	9758037	D3030	Heat Pump [HP-4]	Var Refrig Vol (VRV)	6 TON	Wayside Elementary School / Main Building	Roof	Daikin Industries	REY072	Illegible			
11	9758071	D3030	Split System	Fan Coil Unit, DX	2 TON	Wayside Elementary School / Main Building	Throughout Building						10

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
12	9758073	D3030	Split System Ductless	Single Zone	1.5 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	PUZ-A18NKA7	6XU00448A	2017		
13	9758156	D3030	Split System Ductless [AC-1]	Single Zone	0.75 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	SUZ-KA09NA	63P00869	2017		
14	9758100	D3030	Split System Ductless [AC-10]	Single Zone	1 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	PUY-A12NHA6	41U01148B	2015		
15	9758113	D3030	Split System Ductless [AC-11]	Single Zone	1.5 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	PUZ-A18NKA7	6YU00690A	2016		
16	9758153	D3030	Split System Ductless [AC-12]	Single Zone	1.5 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	PUZ-A18NKA7	6XU00319A	2017		
17	9758122	D3030	Split System Ductless [AC-13]	Single Zone	0.75 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	SUZ-KA09NA	68P01859			
18	9758080	D3030	Split System Ductless [AC-2]	Single Zone	1 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	PUY-A12NHA6	SZU05711A	2016		
19	9758120	D3030	Split System Ductless [AC-3]	Single Zone	0.75 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	SUZ-KA09NA	63P01028			
20	9758130	D3030	Split System Ductless [AC-5]	Single Zone	0.75 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	SUZ-KA09NA	63P00863			
21	9758108	D3030	Split System Ductless [AC-6]	Single Zone	1 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	PUY-A12NHA6	51U06043B	2016		
22	9758032	D3030	Split System Ductless [AC-7]	Single Zone	0.75 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	SUZ-KA09NA	63P01024			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
23	9758118	D3030	Split System Ductless [AC-9]	Single Zone	0.75 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	SUZ-KA09NA	63P00859			
24	9758081	D3030	Split System Ductless [DSS-1]	Single Zone	1.5 - 2 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	Illegible	Illegible			
25	9758090	D3030	Split System Ductless [DSS-2]	Single Zone	1.5 - 2 TON	Wayside Elementary School / Main Building	Roof	Mitsubishi	PUY-A12NHA2	Illegible			
26	9758079	D3050	Pump [P-1]	Distribution, HVAC Heating Water	30 HP	Wayside Elementary School / Main Building	Boiler Room	Armstrong	030180T3E286T-G	NA	2017		
27	9758148	D3050	Pump [P-2]	Distribution, HVAC Heating Water	30 HP	Wayside Elementary School / Main Building	Boiler Room	Armstrong	030180T352861-G	NA	2017		
28	9758070	D3050	Pump [P-3]	Distribution, HVAC Heating Water	10 HP	Wayside Elementary School / Main Building	Boiler Room	Armstrong	4300428-083	NA	2017		
29	9758145	D3050	Pump [P-4]	Distribution, HVAC Heating Water	10 HP	Wayside Elementary School / Main Building	Boiler Room	Armstrong	4300428-083	NA	2017		
30	9758110	D3050	Air Handler [ERU-1]	Exterior AHU	25001 - 30000 CFM	Wayside Elementary School / Main Building	Building Exterior	Innovent	F-LASER-28-8000-AC/IP-1-A	207304	2008		
31	9758098	D3050	Fan Coil Unit	Hydronic Terminal	401 - 800 CFM	Wayside Elementary School / Main Building	Throughout Building				2017		30
32	9758101	D3050	Packaged Unit [DOAS-1]	RTU, Pad or Roof-Mounted	6 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-006-3-0-E709-000: FEJCU0BDBCB0ADD0AHB6000000000X	201702-ANCF12202	2017		
33	9758104	D3050	Packaged Unit [DOAS-2]	RTU, Pad or Roof-Mounted	6 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-006-3-0-E709-000: GEBDU0BDBDB0ADD0AHB6000000000M0X	201702-ANCF12201	2017		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
34	9758163	D3050	Packaged Unit [DOAS-3]	RTU, Pad or Roof-Mounted	16 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-016-3-0-E709-000: UEDDU0BDRE B0ADD0AHB600000000M0X	201702-BNCM12203	2017		
35	9758123	D3050	Packaged Unit [DOAS-4]	RTU, Pad or Roof-Mounted	26 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-026-3-0-E709-000: UE FEU0BDFRG0ADD0AH8600080000M0X	201702 BNCS12206	2017		
36	9758058	D3050	Packaged Unit [DOAS-5]	RTU, Pad or Roof-Mounted	16 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-016-3-0-E709-000: UEDEU0BDDQB0ADD0AHB600000000M0X	201702-BNCM12204	2017		
37	9758138	D3050	Packaged Unit [DOAS-6]	RTU, Pad or Roof-Mounted	9 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-009-3-0-E709-000: UECDU0BDSDBAADD0AHB600000000M0X	201702-ANCQ12200	2017		
38	9758162	D3050	Packaged Unit [ERU-1]	RTU, Pad or Roof-Mounted	26 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-026-3-0-E709-000 VGFDU0BGERG0ADD0AHB6000B0000M0X	201702-BNCS12205	2017		
39	9758107	D3050	Packaged Unit [HV-1]	RTU, Pad or Roof-Mounted	26 TON	Wayside Elementary School / Main Building	Roof	AAON, Inc.	RN-026-3-A-0000-309: VGFDU0BDL SG0A000AHL 6000B000000X	201702-BNGS58967	2017		
40	9758047	D3060	Exhaust Fan [EF-1]	Centrifugal, 24" Damper	2001 - 5000 CFM	Wayside Elementary School / Main Building	Roof	Penn Barry	DX10R	AD8AN90351			
41	9758128	D3060	Exhaust Fan [EF-2]	Centrifugal, 24" Damper	2001 - 5000 CFM	Wayside Elementary School / Main Building	Roof	Penn Barry	DX110	A0 AN08892			
42	9758114	D3060	Exhaust Fan [PRV-1]	Centrifugal, 12" Damper	100 - 1000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	6-075-D-X	14860965			
43	9758046	D3060	Exhaust Fan [PRV-4]	Centrifugal, 28" Damper	5001 - 8500 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	CUE 096-D-X	14860967			
44	9758068	D3060	Exhaust Fan [PRV-5]	Centrifugal, 24" Damper	2001 - 5000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	G-099-A-X	14860968			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
45	9758084	D3060	Exhaust Fan [PRV-6]	Centrifugal, 16" Damper	1001 - 2000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	C-075-D-X	14860966			
46	9758050	D3060	Exhaust Fan [PRV-7]	Centrifugal, 16" Damper	1001 - 2000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	G-085-D-X	14860969			
47	9758087	D3060	Exhaust Fan [RV-1]	Centrifugal, 28" Damper	15001 - 20000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	FGR-20X30-A-BS	68533219-0001	17A		
48	9758089	D3060	Exhaust Fan [RV-2]	Centrifugal, 28" Damper	15001 - 20000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	FGR-20X30-A-BS	68533250-0001	17A		
49	9758144	D3060	Exhaust Fan [RV-3]	Centrifugal, 24" Damper	2001 - 5000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	FGR-14X14-A-BS	68533281-0001	17A		
50	9758117	D3060	Exhaust Fan [SF-1]	Roof or Wall-Mounted, 42" Damper	15001 - 20000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	RBS-2H48-5-X	14861322			
51	9758040	D3060	Exhaust Fan [SF-2]	Roof or Wall-Mounted, 42" Damper	15001 - 20000 CFM	Wayside Elementary School / Main Building	Roof	Greenheck	RBS-2H48-5-X	14861323			
52	9758137	D3060	Supplemental Components	Air Curtain, 5' Wide Non-Heated		Wayside Elementary School / Main Building	Kitchen	Mars	STD 248-1UA-0B	1009932			
53	9758078	D3060	Supplemental Components	Air Curtain, 5' Wide Non-Heated		Wayside Elementary School / Main Building	Hallways & Common Areas	Mars	STD248-1UA-0B	1009933			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D40 Fire Protection													
1	9758112	D4010	Backflow Preventer	Fire Suppression	4 INCH	Wayside Elementary School / Main Building	Boiler Room	Watts	Illegible	Illegible			
2	9758147	D4010	Backflow Preventer	Fire Suppression	4 INCH	Wayside Elementary School / Main Building	Boiler Room	Watts	Illegible	QF-0869			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D50 Electrical													
1	9766755	D5010	Generator	Diesel	130 KW	Wayside Elementary School / Site	Building Exterior	Kohler	200REZXB	SGM32J92X	2017		
2	9758088	D5010	Automatic Transfer Switch	ATS	1200 AMP	Wayside Elementary School / Main Building	FACP Room	Kohler	NA	NA			
3	9758085	D5010	Automatic Transfer Switch	ATS	1200 AMP	Wayside Elementary School / Main Building	FACP Room	Kohler	NA	NA			
4	9758102	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2016		
5	9758155	D5020	Secondary Transformer	Dry, Stepdown	30 KVA	Wayside Elementary School / Main Building	Intermediate Book Closet Electrical Room	Siemens	NA	NA			
6	9758135	D5020	Secondary Transformer	Dry, Stepdown	15 KVA	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2016		
7	9758105	D5020	Secondary Transformer	Dry, Stepdown	225 KVA	Wayside Elementary School / Main Building	Exterior Electrical Room	Siemens	NA	DAK07116359	2007		
8	9758127	D5020	Secondary Transformer	Dry, Stepdown	75 KVA	Wayside Elementary School / Main Building	Electrical Room	Eaton	NA	NA	2016		
9	9758048	D5020	Secondary Transformer	Dry, Stepdown	75 KVA	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2016		
10	9758056	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Wayside Elementary School / Main Building	Electrical Room 214	Eaton	NA	NA	2016		
11	9758140	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Wayside Elementary School / Main Building	Electrical Room	Eaton	NA	NA	2016		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
12	9758133	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Wayside Elementary School / Main Building	Electrical Room 225	Eaton	NA	NA	2016		
13	9758031	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2016		
14	9758146	D5020	Secondary Transformer	Dry, Stepdown	75 KVA	Wayside Elementary School / Main Building	Electrical Room 225	Eaton	NA	NA	2016		
15	9758096	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2016		
16	9758067	D5020	Switchboard	277/480 V	2000 AMP	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2017		
17	9758136	D5020	Switchboard	277/480 V	800 AMP	Wayside Elementary School / Main Building	Exterior Electrical Room	Siemens	NA	NA	2008		
18	9758041	D5020	Distribution Panel	120/208 V	800 AMP	Wayside Elementary School / Main Building	Exterior Electrical Room	Siemens	NA	NA	2007		
19	9758160	D5020	Distribution Panel	120/208 V	800 AMP	Wayside Elementary School / Main Building	Exterior Electrical Room	Siemens	NA	NA	2007		
20	9758059	D5020	Distribution Panel	120/208 V	800 AMP	Wayside Elementary School / Main Building	Exterior Electrical Room	Siemens	NA	NA	2007		
21	9758099	D5020	Distribution Panel	277/480 V	600 AMP	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2017		
22	9758044	D5020	Distribution Panel	277/480 V	800 AMP	Wayside Elementary School / Main Building	FACP Room	Eaton	NA	NA	2017		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
23	9758134	D5020	Distribution Panel	277/480 V	450 AMP	Wayside Elementary School / Main Building	Electrical Room 225	Eaton	NA	NA	2017		
24	9758131	D5020	Distribution Panel	277/480 V	400 AMP	Wayside Elementary School / Main Building	Electrical Room 214	Eaton	NA	NA	2017		
25	9758083	D5020	Distribution Panel	277/480 V	450 AMP	Wayside Elementary School / Main Building	Electrical Room 225	Eaton	NA	NA	2017		
26	9758143	D5030	Variable Frequency Drive	VFD, by HP of Motor	30 HP	Wayside Elementary School / Main Building	Boiler Room	ABB	ACH580-VCR-044A-4+F267+J405	2250701819	2017		
27	9758061	D5030	Variable Frequency Drive	VFD, by HP of Motor	30 HP	Wayside Elementary School / Main Building	Boiler Room	ABB	ACH550-VDR-045A-4	2171205117	2017		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D70 Electronic Safety & Security													
1	9758109	D7050	Fire Alarm Panel	Fully Addressable		Wayside Elementary School / Main Building	FACP Room	Est	Est3	NA			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
E10 Equipment													
1	9758036	E1030	Foodservice Equipment	Commercial Kitchen, 3-Bowl		Wayside Elementary School / Main Building	Kitchen						
2	9758039	E1030	Foodservice Equipment	Convection Oven, Double		Wayside Elementary School / Main Building	Kitchen	Blodgett	No dataplate	No dataplate			
3	9758119	E1030	Foodservice Equipment	Dairy Cooler/Wells		Wayside Elementary School / Main Building	Kitchen	Delfield	KCFT-60	1610150002826			
4	9758125	E1030	Foodservice Equipment	Dairy Cooler/Wells		Wayside Elementary School / Main Building	Kitchen	Beverage-Air Corporation	STF58Y-1-S	NA			
5	9758052	E1030	Foodservice Equipment	Exhaust Hood, 3 to 6 LF		Wayside Elementary School / Main Building	Kitchen	CaptiveAire Systems	6630 VHB	NA			
6	9758093	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Wayside Elementary School / Main Building	Kitchen	Metro	NA	C5HME026472	2017		
7	9758062	E1030	Foodservice Equipment	Refrigerator, 1-Door Reach-In		Wayside Elementary School / Main Building	Kitchen	Contential	DL1R-SS-HD	156A8373			
8	9758057	E1030	Foodservice Equipment	Steamer, Freestanding		Wayside Elementary School / Main Building	Kitchen	Delfield	MARK7000-400Y22W3	1610150002827			
9	9758149	E1030	Foodservice Equipment	Walk-In, Condenser for Refrigerator/Freezer		Wayside Elementary School / Main Building	Roof	Bally	Illegible	Illegible			
10	9758074	E1030	Foodservice Equipment	Walk-In, Condenser for Refrigerator/Freezer		Wayside Elementary School / Main Building	Roof	Bally	BEHA010E6-HT3B-7091	172103090			
11	9758086	E1030	Foodservice Equipment	Walk-In, Evaporator for Refrigerator/Freezer		Wayside Elementary School / Main Building	Kitchen	Bally	Inaccessible	Inaccessible			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
12	9758064	E1030	Foodservice Equipment	Walk-In, Evaporator for Refrigerator/Freezer		Wayside Elementary School / Main Building	Kitchen	Bally	Inaccessible	Inaccessible			
13	9758129	E1030	Foodservice Equipment	Walk-In, Freezer		Wayside Elementary School / Main Building	Kitchen	Bally	No dataplate	No dataplate			
14	9758045	E1030	Foodservice Equipment	Walk-In, Refrigerator		Wayside Elementary School / Main Building	Kitchen	Bally	No dataplate	No dataplate			